## PROFORMA FOR THE STRUCTURAL AUDIT OF SCHOOL BUILDING

## PART - I

(To be filled	by the	Head	School	/ Institute	)
---------------	--------	------	--------	-------------	---

1)	Name of the School	ţ-	Dream Dale Public Sc	hool					
2)	Location	ţ-	Sindhi Colony Road ( Bhandara. (Maharash		га Вура	ss) Gurunani	Ward		
3)	Plot Area	·		i fag					
	Number of Floor	1 -	G + 1	4					
5)	Year of Constuction of Bui	lding :-	2021						
5)	If the building has been of following details may be		ted under the supervi	sion of	the qua	lified Engine	er, the		
							i li		
a)	Name of the Engineer with	n qualif	ication :- Mr. Pramod	Gurmu	le (Diple	oma Civil Eng	ineer)		
0)	Address of Engineer :- Jagnade Chowk, Nagpur.								
:)	Set of Structural drawings	used in	construction, if availa	ble :-	Yes				
7) '	Whether the building has b	een co	onstructed for the purp	oose					
a) !	School			:-	Yes	Se O NE I			
o) i	Residental Purpose and cor	nverted	for use as a School	:-	No				
3)	Materials used for roofs				á				
a) !	R.C.C Slab / R.B.C. Slab		- 14 A	:-	Yes				
o)	R.S.Joint & Battons			:-	No				
c) \	Wooden Joint & Bottoms	*		:-	No				
9)	Materials used for walls								
a)	Mud Mortar			:-	No				
b)	Cement Mortar			:-	Yes				
c) (	Lime Mortar			:-	No .				
10	) Flooring								
a)	Conglomerate			;-	No				
b)	Terrazo			:-	Yes				
c)	Brick Paving			:-	No				
11	) A detailed drawing indica	iting di	mension of the rooms	along	with size	e and locatio	n of door		
	and Windows.		1964 0198						
* 1,	I FOLLHERY UP AND IF		Lucida Salidada a Lucida Salidada		and.				
			AND ADDRESS OF THE PARTY OF THE	200					

SOUTH Commit bh ees age

(To be filled by the S.D. Black)

a) I have visited the above mentioned school on dated 04/05/19022 Pand Rave visually inspected it form all angles of saftey and find it fit for normal use as School buildings.

- b) In case any addition / alteration or expression and modifications to this buildings is to carried out, the same be carried out under the supervision of a qulified Engineer and this certificate may be rebotained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls / foundations or sagging of roofs etc. immediate ispection of the undersigned by arranged to check the stability and saftey of the building.
- d) This building can be safety occupied of normal use upto (indicated upto which it can be used) 40 years. (if proper maintaince)

Place :- Bhandara

Date: 04/05/2022

Dream Dale Public School Curunanak Ward, res Rd., Ehandara-441904